

Inspection Photos
Location Name: Wingo, C.E. 2
Location ID: 323256




Photo 1 Location.



Photo 2 Wellhead.

Inspection Photos
Location Name: Wingo, C.E. 2
Location ID: 323256



Photo 3 Well site sign.

Photo 4 Pump jack.

Inspection Photos
Location Name: Wingo, C.E. 2
Location ID: 323256



Photo 5 Stained soil by the gas engine.

Photo 6 stained soil by the wellhead.