

Inspection Photos

10/28/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313152

Inspection Doc: 719200380

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313152



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313152



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313152



Photo 3: Photos showing an example of the eastern portion of the location. Vegetation is not progressing towards 1004 reclamation requirements; some areas remain predominantly bare and uniformity is not evident. Additional seeding may be required to meet 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313152



Photo 4: Photos showing an example of the north-central portion of the location. Vegetation is not progressing towards 1004 reclamation requirements; uniformity is not evident. Additional may be required to meet 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313152



Photo 5: Photo showing an example of utility equipment that remains at the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313152



Photo 6: Photos showing an example of the reference area, located to the north of the location. Reference areas are characterized by big sagebrush shrublands; big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources