

FORM  
INSPRev  
X/20

# State of Colorado

## Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2025

Submitted Date:

11/04/2025

Document Number:

719200380

### FIELD INSPECTION FORM

Loc ID 313152 Inspector Name: Gaasche, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10396  
Name of Operator: SWN PRODUCTION COMPANY LLC  
Address: P.O. BOX 12359  
City: SPRING State: TX Zip: 77391-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		karen_manerotis@swn.com	
Gee, Elizabeth	(832) 796-2873	liz_gee@swn.com	<a href="#">All Inspections</a>
, SWN		swnsandwash@swn.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264314	WELL	PA	05/17/2022	CBM	081-07095	WALKER 3-5	RI
313152	LOCATION	CL			-	WALKER 7-93-3 PAD5	RI

**General Comment:**

On 10/28/2025, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at SWN Production Company LLC's Walker 7-93-3/Pad 5 location in Moffatt County, Colorado.

It was observed in this inspection that reclamation has not been completed pursuant to 1004 requirements.

The following compliance issues were observed during this inspection:

- Utility equipment remaining
- 1004 reclamation (uniformity)

Refer to the Reclamation and COGCC Comments section of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

**Inspected Facilities**

Facility ID: 264314 Type: WELL API Number: 081-07095 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 313152 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed **Fail** \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Conduct reclamation on the location in accordance with 1004 rules including, but not limited to: removal of utility equipment, recontour/regrade and establish vegetation with total perennial, non-invasive uniform plant cover of at least 80% of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district.

Comply with Rule 1002.f and ensure erosion controls are implemented to stabilize the seeded soil.

Comply with 1004 Rules and remove utility equipment on, and leading to the Location.

Ongoing stormwater and weed management required until Final Reclamation has passed.

Overall Final Reclamation **Fail** Well Release on Active Location  Multi-Well Location

**ECMC Comments**

Comment	User	Date
<p><b>RECLAMATION COMMENTS:</b> Pursuant to Form 6(s) #403143556, well API #05-081-07095 was plugged and abandoned on 05/17/2022. Form 4 #403799546 stating final reclamation complete was received by ECMC on 06/04/2024.</p> <p>The location is primarily composed of rubber rabbitbrush and intermediate wheatgrass. No noxious weeds or undesirable plant species were observed on the location during the time of inspection. Some portions of the location, such as the north-central and eastern areas, are not progressing towards 1004 reclamation standards. These areas remain predominantly bare and are at-risk of erosion and weedy plant establishment. Additional seeding may be necessary to achieve 1004 requirements in these areas. It was also observed that species planted do not reflect species within the adjacent undisturbed reference areas, or vegetation that existed pre-disturbance; records show surface owner approved of the mix.</p> <p>Utility equipment that is no longer in use remains at the location. Utility equipment is associated with the O&amp;G Location for O&amp;G operations, and the corrective action requirements for removal remains applicable. It is the ECMC's expectation that SWN will coordinate with the equipment's owner for removal.</p> <p>The access road pre-existed the location.</p> <p>Pursuant to Rule 1004.a, all debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well. All access roads to plugged and abandoned wells and associated production facilities shall be closed, graded and recontoured. Well locations, access roads and associated facilities shall be reclaimed. As applicable, compaction alleviation, restoration, and revegetation of well sites, associated production facilities, and access roads shall be performed to the same standards as established for interim reclamation under Rule 1003. All other equipment, supplies, weeds, rubbish, and other waste material shall be removed. All such reclamation work shall be completed within twelve (12) months on non-crop land after plugging a well or final closure of associated production facilities.</p>	gaaschee	11/04/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719200381	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317144">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317144</a>