

# Work Completion Report

Contractor: H2 Enterprises (H2)

## JOB DETAILS

| Job Name                                | Month/Season | Completed By | Completion Date |
|---|--------------|--------------|-----------------|
| WETHINGTON WILLIAM GU 1 (2025 Seasonal) | Fall         | Dusty Hayden | 9/19/2025       |

| Work Summary      | Reclamation Type | Land Use |
|-------------------|------------------|----------|
| Mowed and drilled | Final Maint      | Pasture  |

| One-Call Number | Red Zone Rep | Red Zone Date |
|-----------------|--------------|---------------|
|                 |              |               |

## WORK TASK

| Task Name                     | Priority | COGCC Compliance | Task Location and Notes/Instructions   |
|-------------------------------|----------|------------------|--|
| Final Reclamation Maintenance |          | No               | Location(s): WILLIAMS WETHINGTON GAS UNIT 1<br>Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task |

## COMPLETION DETAILS

Total Area Affected: **87,120 sq ft**  
 Seed Mix: **Dryland Pasture (30.00 lbs)**  
 Crop Type:  
 Soil Type: **Sandy Loam**  
 Stabilization Date: **9/19/2025**  
 Seeding Date: **9/19/2025**  
 Mulch: **None**  
 Straw Bales: **NA**  
 Soil Amendment Type: **None**  
 Soil Amendment Rate: **NA**  
 Imported Top Soil: **NA**  
 Top Soil Source: **NA**  
 General Notes: **Oxrm1656**

PHOTOS

Photo Name: Seed Mix  
Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: A

Description:



Photo Name: B

Description:



Photo Name: C

Description:



Photo Name: D

Description:

