

Inspection Photos

10/29/2025

Operator: Quicksilver Resources Inc #10255

Location ID: 313181

Inspection Doc: 719200391

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Operator Name: Quicksilver Resources Inc #10255
Location ID: 313181



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313181



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313181



Photo 3: Photos showing an example of Scotch thistle, a List B noxious weed, is present throughout the site. It does not appear as though weeds have been managed in 2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313181



Photo 4: Photos the show access road has not been reclaimed in accordance with 1004 Rules- culverts remaining. Gravel has not been removed; road has not been decompacted, recontoured/regraded and/or reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313181



Photo 5: Photos the show access road has not been reclaimed in accordance with 1004 Rules- culverts remaining. Gravel has not been removed; road has not been decompacted, recontoured/regraded and reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313181



Photo 6: Photo showing an example of utility equipment on and leading to the location that has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313181



Photo 7: Photos showing an example of the reference area, located to the east of the location looking south. Reference areas are characterized by big sagebrush shrublands, and big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources