

Inspection Photos

10/29/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313350

Inspection Doc: 719200393

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313350



Photo 1: Photos showing an overview of the location looking northeast and southeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313350



Photo 2: Photos showing an overview of the location looking northwest and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313350



Photo 3: Photo showing an overview from the southwestern end of the location; the location has not been reclaimed per 1004 reclamation requirements. A variance to waive reclamation of the location and access road is pending Commission decision.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313350



Photo 4: Photos showing a sign with incorrect Operator information and some debris is present at the location. Comply with Rules 606.a. and 1004.a. Removal is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313350



Photo 5: Photos showing the access road leading to the location. The access road has not been reclaimed per 1004 reclamation requirements; gravel and compaction is evident. A variance to waive reclamation of the location and access road is pending Commission decision.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313350



Photo 6: Photos showing an example of the reference area, located to the northeast of the location. Reference areas are characterized by big sagebrush shrublands, and big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources