

# Inspection Photos

10/29/2025

Operator: Quicksilver Resources Inc #10255

Location ID: 313334

Inspection Doc: 719200395

Moffatt County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313334



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313334



**Photo 2:** Photos showing an overview of the location looking southeast and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313334



**Photo 3:** Photos showing an example of Scotch thistle, a List B noxious weed, that is present throughout the location. Basal rosettes and new growth are apparent. The location is at-risk of being overtaken by Scotch thistle.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313334



**Photo 4:** Photo showing an example of the eastern areas of the location. Areas are not progressing towards 1004 revegetation standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313334



**Photo 5:** Photo showing an example of utility equipment on and leading to the location that requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Quicksilver Resources Inc #10255

Location ID: 313334



**Photo 6:** Photos showing riser equipment that remains at the PA'd well marker and requires removal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources