

Inspection Photos

10/29/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313339

Inspection Doc: 719200397

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 3: Photos showing an example of Scotch thistle, a List B noxious weed, that is present throughout the site. Basal rosettes and new growth is present. Weeds do not appear to have been managed in 2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 4: Photos showing a sediment trap that is present on the southeast corner of the location. The location has not been reclaimed pursuant to 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 5: Photos taken from the Location entrance at the south end of the Location. Photo shows areas of the Location that has not been reclaimed in accordance with 1004 requirements; areas have not achieved a uniform vegetative establishment; gravel and compaction remains evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 6: Photo taken on the west end of the location showing an example of utility equipment on and leading to the location remains and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 7: Photo showing some areas throughout the location are patchy and have not achieved uniformity; however, plant establishment is evident and these areas may need more time to develop.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313339



Photo 8: Photos showing an example of the reference area, located to the south of the location. Reference areas are characterized by big sagebrush shrublands, and big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources