

Final Reclamation Inspection

November 6, 2025

Operator: GRIZZLY OPERATING LLC- #443741

Location ID: 443741

Inspection Document #: 697506043

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Goza Beneficial Reuse Area
Location ID: 443741



Photo 1. Google Earth aerial imagery from 6/19/2014 prior to the use of the Land Application Site. The red polygon is the planned area for the Goza Beneficial Reuse Area.



Inspection Photos
Location Name: Goza Beneficial Reuse Area
Location ID: 443741



Photo 2. Google Earth aerial imagery from 7/17/2019 after the use of the Land Application Site (LAS) ended in April 2016. The red polygon is the area for the Goza Beneficial Reuse Area. A portion of the northern LAS no longer is incorporated into crop production and appears to be in an agricultural use. Areas of the LAS appear to be uniform with the surrounding reference crop areas and do not appear to indicate any unrestored subsidence.



Inspection Photos

Location Name: Goza Beneficial Reuse Area

Location ID: 443741



Photo 3. Google Earth aerial imagery from 3/2/2025. See comments under Photo 2.

