

Inspection Photos

10/29/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313257

Inspection Doc: 719200401

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313257



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313257



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313257



Photo 3: Photos showing an example of Scotch thistle, a List B noxious weed, that is present throughout the site. Basal rosettes are present throughout the location and on the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313257



Photo 4: Photos showing the access road leading to the location has not been reclaimed pursuant to 1004 reclamation requirements; gravel and compaction is evident. Knotweed, an undesirable plant species, is present on the road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313257



Photo 5: Photos showing an example of the reference area, located to the west of the location. The reference area is characterized by big sagebrush shrublands.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources