

Inspection Photos

API: 061-06277

Operator: **RENEGADE OIL & GAS COMPANY LLC**

Inspection Date: 11/4/2025

County: Kiowa



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the location. The dark brown vegetation are undesirable weeds. The perennial vegetation has not re-established.



Inspection Photos



Photo 2. Facing north toward the location. The dark brown vegetation are undesirable weeds. The perennial vegetation has not re-established.



Inspection Photos



Photo 3. Facing south at the location.



Inspection Photos



Photo 4. Facing south at the location. It appears were reseeded with presence of straw mulch and drill rows.

