

Inspection Photos

API: 061-06166

Operator: **RENEGADE OIL & GAS COMPANY LLC**

Inspection Date: 11/4/2025

County: Kiowa



Inspection Photos



Photo 1. Facing west toward the wellsite.



Inspection Photos



Photo 2. Unused areas of the location have had recent reclamation work.



Inspection Photos



Photo 3. Facing toward the west side of the location.



Inspection Photos



Photo 4. Facing toward the tank which is fenced and maintained. Currently not in use since well is TA'd.

