

# Inspection Photos

10/29/2025

**Operator:** SWN Production Company LLC

#10396

**Location ID:** 313259

**Inspection Doc:** 719200403

Moffatt County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 3:** Photo showing an overview of the location looking northwest. Crop establishment appears thin and soil lighter in some areas. A follow-up inspection will be conducted during the growing season to determine crop progression towards 1004 requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 4:** Photo showing signage with incorrect Operator information is present at the location. Removal is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 5:** Photos showing the access road that runs along the southeastern end of location. The access road has not been reclaimed; gravel and compaction is evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 6:** Photos showing an example of a culvert that remains along the access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313259



**Photo 7:** Photos showing the reference area, located in the south-central portion of the crop field.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources