

Inspection Photos

10/29/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313258

Inspection Doc: 719200406

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313258



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313258



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313258



Photo 3: Photos showing the access road to the location has not been reclaimed; gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313258



Photo 4: Photos showing an example of Scotch thistle basal rosettes that have established at the entrance to the location near the access road. Scotch thistle is a List B noxious weed species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources