

# Final Reclamation Inspection

October 16, 2025

Operator: DIVERSIFIED OPERATING CORPORATION - 24461

Location ID: 408435

Inspection Document #: 718800957

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LONG DRAW #1-22  
Location ID: 408435



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: LONG DRAW #1-22  
Location ID: 408435



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.





Inspection Photos  
Location Name: LONG DRAW #1-22  
Location ID: 408435



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including Kochia (*Bassia scoparia*).



**Photo 6.** Photo taken of the tank battery location, facing northwest. Photo illustrates that midstream equipment remains on the location and final reclamation does not meet Rule 1004 standards as weedy annual vegetation was observed across the location.





Inspection Photos  
Location Name: LONG DRAW #1-22  
Location ID: 408435



**Photo 7.** Photo taken of the tank battery location, facing west.  
See comments under Photo 6.



**Photo 8.** Photo taken of the tank battery location, facing south.  
See comments under Photo 6.





Inspection Photos  
Location Name: LONG DRAW #1-22  
Location ID: 408435



**Photo 9.** Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass vegetation.

