

Interim Reclamation Inspection

October 16, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 470250

Inspection Document #: 718800945

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-Lost Creek/State
Location ID: 470250



Photo 1. Photo taken of the tank battery location, facing west. Photo illustrates the tank battery is full of weedy annual vegetation, including kochia (*Bassia scoparia*).



Photo 2. Photo taken of the tank battery location, facing north. See comments under Photo 1.



Inspection Photos
Location Name: HSR-Lost Creek/State
Location ID: 470250



Photo 3. Photo taken of the tank battery location, facing west. Photo illustrates weedy annual vegetation across the location.



Photo 4. Photo taken of the tank battery location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HSR-Lost Creek/State
Location ID: 470250



Photo 5. Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*).