

Interim Reclamation Inspection

October 16, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 330308

Inspection Document #: 718800947

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-LOST CREEK/STATE #14-11

Location ID: 330308



Photo 1. Photo taken of the well location, facing southwest. Photo illustrates that fencing is stacked on the location and a porta potty is laying on its side.



Photo 2. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos

Location Name: HSR-LOST CREEK/STATE #14-11

Location ID: 330308



Photo 3. Photo taken of the well location, facing north. Photo illustrates that fencing is partially removed and weedy annual vegetation is established across the location, including kochia (*Bassia scoparia*).



Photo 4. Photo taken of the well location, facing north. See comments under Photo 3.

