

Interim Reclamation Inspection

October 16, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 330171

Inspection Document #: 718800953

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-LOST CREEK #12-14
Location ID: 330171




Photo 1. Photo taken of the well location, facing east. Photo illustrates that weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well and tank battery location, facing southeast. See comments under Photo 1.



Inspection Photos
Location Name: HSR-LOST CREEK #12-14
Location ID: 330171



Photo 3. Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



Photo 4. Photo taken of ground cover at the location. Photo illustrates kochia (*Bassia scoparia*).

