

Final Reclamation Inspection

October 16, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 409428

Inspection Document #: 718800939

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-LOST CREEK #7-11
Location ID: 409428




Photo 1. Google Earth Aerial Imagery from September 21, 2023 depicting the well location after plugging operations. Photo illustrates the location and surrounding reference areas are located in degraded prairie dog habitat.



Inspection Photos
Location Name: HSR-LOST CREEK #7-11
Location ID: 409428



Photo 2. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but the location is dominated by weedy annual vegetation and does not meet Rule 1004 standards.



Photo 3. Photo taken of the well location, facing east. See comments under Photo 2.

Inspection Photos
Location Name: HSR-LOST CREEK #7-11
Location ID: 409428



Photo 4. Photo taken of the well location, facing south. See comments under Photo 2.



Photo 5. Photo taken of the well location, facing west. See comments under Photo 2.



Inspection Photos
Location Name: HSR-LOST CREEK #7-11
Location ID: 409428



Photo 6. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation dominates the location.




Photo 7. Photo taken of the reference area to the well location, east of the location, facing east. Photo illustrates weedy annual vegetation.

