

Final Reclamation Inspection

October 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 309727

Inspection Document #: 718800965

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COOPER #23-15
Location ID: 309727



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place. However, vegetation has not established to Rule 1004 standards at the location. Bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*), were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: COOPER #23-15
Location ID: 309727



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: COOPER #23-15
Location ID: 309727



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing south, towards the location. Photo illustrates that the access road does not meet Rule 1004 standards as gravel, bare ground, and weedy annual vegetation were observed across the road.

Inspection Photos
Location Name: COOPER #23-15
Location ID: 309727



Photo 7. Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass vegetation.

