

Inspection Photos on 11/5/25  
Operator: Renegade Oil & Gas  
Location Name: Walker 1  
API: 05-099-06164



1. Tubing on south side of wellhead needs removed. Stained soil around wellhead needs remediated



2. Debris around pumping unit needs cleaned up and removed from location

Inspection Photos on 11/5/25  
Operator: Renegade Oil & Gas  
Location Name: Walker 1  
API: 05-099-06164



3. Labeling on tanks are missing



4. Treater, ECD and VGS. Misc debris inside the fence needs removed