

Inspection Photos

10/30/2025

Operator: SWN Production Company LLC

#10396

Location ID: 425038

Inspection Doc: 719200412

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 1: Photos showing an overview of the location looking northeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 2: Photos showing an overview of the location looking southeast and northwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 3: Photos showing old signage debris with incorrect Operator information is present at the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 4: Photos showing cut slopes remain and the location has not been regraded or recontoured pursuant to 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 5: Photos showing damaged rock socks and stormwater controls that remain on the southern and southwestern end of the location. Debris requires removal and stormwater controls have not been reclaimed pursuant to 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 6: Photo showing pipe debris that is present on the eastern cut slope and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 7: Photos showing stormwater controls remain on the west-central location. Stormwater controls have not been reclaimed pursuant to 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 8: Photos showing stormwater controls remain on the west-central location. Stormwater controls have not been reclaimed pursuant to 1004 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 9: Photos showing prickly Russian thistle (left), an undesirable weedy plant species, is present on the southern portion of the location. Scotch thistle basal rosettes (right), are present on the southwestern portion of the location. Weed management is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 10: Photos showing the southern access road leading to the location has been reclaimed; gravel has been removed, soils have been decompacted and plant establishment is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 425038



Photo 11: Photos showing the reference area, located to the north of the location. The reference area is characterized by big sagebrush shrubland.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources