

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 09/10/2025 Document Number: 404271463

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 95620 Contact Person: Brent Bongers Company Name: WESTERN OPERATING COMPANY Phone: (361) 9355633 Address: 1165 DELAWARE STREET #200 Fax: () City: DENVER State: CO Zip: 80204 Email: bbongers@impetroresources.com

Identification Information

API Number: 05 - - ECMC Facility ID: 119666 Initial Form 19 or 27 Document number: Facility Name: BOBCAT "D" UNIT Facility Number: Facility Type: PIT Location QtrQtr: SWNW Section: 9 Township: 1S Range: 56W Meridian: 6 County: WASHINGTON Field Name: BOBCAT Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS INC. Agent Name: Evan Sky Title: Staff Scientist Phone Number: 9708292232 Email: esky@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 05/29/2025 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772371 Facility Name: BOBCAT "D" UNIT 909J FACILITY Facility Type: PIT Location: QtrQtr: NWSW Sec: 9 Twp: 1S Range: 56W Meridian: 6 County Name: WASHINGTON Latitude: 39.985215 Longitude: -103.661823

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 128253 Document Name: EDD File Name: 2025_0529_Bobcat_EDD AA23811.xlsx SampleType: Matrix: Facility ID: 772371 Sample ID: 668937 Sample Name: BOBCAT IMPETRO Sample Date: 05/29/2025 Collection Point: Tank Matrix: WATER Pre Post: Rule 909.j subsequent sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Elevation Diagnostics Lab Sample ID: AA23811

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772371	404271490	2025_0529_Bobcat_AA2381 1.pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
668937	121-06583	BOBCAT D SAND UNIT 20	Rule 909.j subsequent sample
668937	121-06592	BOBCAT D SAND UNIT 18	Rule 909.j subsequent sample
668937	121-06634	BOBCAT D-SAND UNIT 6	Rule 909.j subsequent sample

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	11/10/2025
Environmental Data	RTD - Collection Point does not align with PrePost or Facility Type.	09/08/2025
Total: 2 comment(s)		