

Audit Photos

Location Name: UTAH GAS OP LTD DBA UTAH GAS CORP, ADAMS-67S104W/11SWNW

Location ID: 323889

Date: 10/30/2025



Location Overview – Photo #01322



Location – Photo #01324

Audit Photos

Location Name: UTAH GAS OP LTD DBA UTAH GAS CORP, ADAMS-67S104W/11SWNW

Location ID: 323889

Date: 10/30/2025



Location – Photo #01326



Location – Photo #01323

Audit Photos

Location Name: UTAH GAS OP LTD DBA UTAH GAS CORP, ADAMS-67S104W/11SWNW

Location ID: 323889

Date: 10/30/2025



Lack of Stabilization – Photo #01325