

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 10/09/2025 Document Number: 404284987

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10779 Contact Person: Spencer Jackson Company Name: SCOUT ENERGY MANAGEMENT LLC Phone: (972) 965-5580 Address: 13800 MONTFORT DRIVE SUITE 100 Fax: ( ) City: DALLAS State: TX Zip: 75240 Email: spencer.jackson@scoutep.com

Identification Information

API Number: 05 - - ECMC Facility ID: 102542 Initial Form 19 or 27 Document number: Facility Name: COLLECTION STATION 20 Facility Number: Facility Type: PIT Location QtrQtr: Section: 21 Township: 2N Range: 102W Meridian: 6 County: RIO BLANCO Field Name: RANGELY Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: SCOUT ENERGY MANAGEMENT LLC Agent Name: Spencer Jackson Title: Senior HSE Specialist Phone Number: 972-965-5580 Email: spencer.jackson@scoutep.com

Rule 909.J Inspection Information

Date the Pit was Inspected 06/24/2025 On inspection the Pit was: [X] Unlined [ ] Lined [ ] Fenced [ ] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 102542 Facility Name: COLLECTION STATION 20 Facility Type: PIT Location: QtrQtr: Sec: 21 Twp: 2N Range: 102W Meridian: 6 County Name: RIO BLANCO Latitude: 40.132073 Longitude: -108.858228

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 128616 Document Name: CS #20 TENORM Analysis File Name: L1866469.xlsx SampleType: Matrix: Facility ID: 102542 Sample ID: 669344 Sample Name: Collection Station #20 TENORM Analysis Sample Date: 06/03/2025 Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: L1866469-01

Batch ID: 130704 Document Name: CS #20 Chemical Analysis File Name: L1873159.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 102542 Sample ID: 671582 Sample Name: Collection Station #20 Chemical Analysis Sample Date: 06/24/2025

Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: Pace Analytical Lab Sample ID: L1873159-01

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
102542	404284989	L1866469.pdf	Analytical Laboratory Report	PDF
102542	404384870	L1873159.pdf	Analytical Laboratory Report	PDF
102542	404284988	L1873159.pdf	Analytical Laboratory Report	PDF

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

**General Comments**

<b>User Group</b>	<b>Comment</b>	<b>Comment Date</b>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. The EDD contained duplicates of bromide, chloride, fluoride, nitrite, nitrate, and sulfate which were subsequently deleted.	11/10/2025
Environmental Data	RTD to add naphthalene	10/08/2025
Environmental Data	RTD - Rule 909j requires sample Facility ID is for well, not pit.	09/09/2025

Total: 3 comment(s)