

Inspection Photos

Operator: **SG INTERESTS I LTD – 77330**

Location Name: **FEDERAL 1-25-10-91R**

Location ID: **324478** API #: **05-051-06067**

Inspection Date: **11/5/2025** Inspection Doc#: **693809010**



Wellhead with pump jack, fence and sign



Separator and Meter Housing

Inspection Photos

Operator: **SG INTERESTS I LTD – 77330**

Location Name: **FEDERAL 1-25-10-91R**

Location ID: **324478** API #: **05-051-06067**

Inspection Date: **11/5/2025** Inspection Doc#: **693809010**



Nov 5, 2025 at 2:01:04 PM
 +39.155921, -107.495681
 297° NW
 Gunnison County
 Energy & Carbon Management Commission

Tank Battery




Plate Size		Test Date				
IN	OUT	DATE	SAMPLE	CAL	SPEC GRAV	
0.500	CHECKED	7.4.16	7.4.16	7.4.16	0.666	
11	✓	10.11.16	10.11.16	10.11.16	0.6875	
11	✓	7.3.17	7.3.17	7.3.17	0.7022	
11	✓	7.3.18	7.3.18	7.3.18	0.6876	
0.500	✓	6-3-19	6-3-19	6-3-19	0.6999	
11	✓	6-12-20	6-12-20	6-12-20	0.6667	
11	✓	5-19-21	5-19-21	5-19-21	0.6926	
0.375	0.500	6-1-21	6-1-21	6-1-21	0.6827	
11	✓	11-4-21	11-4-21	11-4-21	0.6870	
11	✓	6-7-22	6-7-22	6-7-22	0.6851	
11	✓	7-7-23	7-7-23	7-7-23	0.6860	
11	✓	6-11-24	6-11-24	6-11-24	0.6876	
11	✓	6-11-25	6-11-25	6-11-25	0.6835	
11	✓	10-17-25	10-17-25	10-17-25	0.6892	
11	✓	6-11-25	6-11-25	6-11-25	0.6811	
11	✓	10-17-25	10-17-25	10-17-25	0.6821	

Nov 5, 2025 at 2:01:51 PM
 +39.155956, -107.495591
 10° N
 Gunnison County
 Energy & Carbon Management Commission

Calibration card