

Inspection Photos
Location: Riley Gulch Tank Farm
Location ID: 435158, Spill ID 492163



Photo 4 – Standing water in containment area at Tank Battery



Photo 5 – Rocks, debris, and standing water on liner in containment area



Photo 6 – Signage on tank, facing North from Southeast corner of Battery

Inspection Photos
Location: Riley Gulch Tank Farm
Location ID: 435158, Spill ID 492163



Photo 7 – Facing East from West Side of Tank Battery



Photo 8 – Wildlife burrow under containment



Photo 9 – Trash in and around earthen berm on South side of Tank Battery