

# Inspection Photos

API: 061-06271

Operator: **SAMSON OIL COMPANY**

Inspection Date: 11/4/2025

County: Kiowa



## Inspection Photos



**Photo 1.** Facing northwest toward the location.



## Inspection Photos



**Photo 2.** West side of the location northwest. This area is bare of vegetation and appears to have impacted soils..



## Inspection Photos



**Photo 3.** Facing back to the southeast toward bare area shown in previous photo.



## Inspection Photos



**Photo 4.** East side of the location facing west. The desirable perennial vegetation has not established to reference area levels.



## Inspection Photos



**Photo 5.** Facing south toward the surrounding native Blur grama prairie.

