

# Inspection Photos

11/10/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 335743

**Inspection Doc:** 719200423

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335743



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335743



**Photo 2:** Photos showing an overview of the location looking east and northwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335743



**Photo 3:** Photos showing sediment trap on the northwestern corner of the location appears to be laden with sediment and has reached capacity. Comply with 1002.f. and maintain stormwater BMPs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335743



**Photo 4:** Photos showing perimeter wattles are in disrepair, overtopped with sediment or no longer functioning. Maintenance is required. Comply with 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335743



**Photo 5:** Photos showing interim areas at the location are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources