

Inspection Photos
Location Name: Castor LC27-72HN
Location ID: 422413



Photo 1 – Location Sign – Unused Automation Equipment

Photo 2 – Gas Meters

Inspection Photos
Location Name: Castor LC27-72HN
Location ID: 422413



Photo 3 – Unused Pipe



Photo 4 – Unused Pipe and Day Tank

Inspection Photos
Location Name: Castor LC27-72HN
Location ID: 422413



Photo 5 – Trash

Photo 6 – Location Overview

Inspection Photos
Location Name: Castor LC27-72HN
Location ID: 422413



Photo 7 – Well Site Overview

Photo 8 – Well Site