

# Inspection Photos

September 9th, 2025

Operator: Noble

Location ID: 311361

Inspection Document #: 714002548

County: Weld

Corey McDonough - Southwest  
Reclamation Specialist




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Schmidt 19-15G  
Location ID: 311361



**Photo 1.** Aerial view of the well pad (highlighted in red), Access road (highlighted in black) and tank battery (highlighted in blue). Note: Tank battery is associated with the Schmidt 19-10G well API #123-25440 under location ID #327590.

Inspection Photos  
Location Name: Schmidt 19-15G  
Location ID: 311361



**Photo 2.** Aerial view of the well pad and access road taken with a drone during the time of the inspection from the southern edge facing north. Note: crop vegetation at the well pad and access road appears consistent with adjacent reference areas.