

Inspection Photos

September 9th, 2025

Operator: Noble

Location ID: 327598

Inspection Document #: 714002550

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McMillen G19-32D
Location ID: 327598



Photo 1. Aerial view of the well pad (highlighted in red), Access road (highlighted in black) and tank battery (highlighted in blue). Note: Tank battery is associated with its own location ID #488847.

Inspection Photos
Location Name: McMillen G19-32D
Location ID: 327598



Photo 2. Aerial view of the well pad and access road taken with a drone during the time of the inspection from the southern edge facing north. Note: shut in well remains on location. No evidence of the abandoned well on location.