

# Inspection Photos

11/10/2025

**Operator:** QB Energy Operating LLC #10844

**Location ID:** 334942

**Inspection Doc:** 719200437

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334942



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334942



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334942



**Photo 3:** Photos showing what appears to be a sediment trap or stormwater control at the southern end of the location are overtaken with debris. Comply with 1002.f. and maintain stormwater controls.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334942



**Photo 4:** Photos showing an example of vehicle tracking that is occurring on the working pad surface; gravel appears to be sparse in some areas. Maintenance is required; comply with 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334942



**Photo 5:** Photos showing interim areas at the location are composed of desirable, perennial vegetation and is progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources