

Final Reclamation and Stormwater Inspection

November 5, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 311316

Well Name: VONASEK #5

Inspection Document #: 718601166

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: VONASEK #5
Location ID: 311316



Photo 1. Looking south down the access road towards the wellhead. Undesirable weeds such as kochia and russian thistle are overgrown on the access road.



Photo 2. Looking south across the location. A pumpjack is disassembled on location.



Inspection Photos
Location Name: VONASEK #5
Location ID: 311316



Photo 3. Looking south across the location from the north side. Unused equipment throughout the location. Interim area has desirable vegetation establishment.



Photo 4. Photo taken at the wellhead. Undesirable weeds such as russian thistle present on location and touching equipment.



Inspection Photos
Location Name: VONASEK #5
Location ID: 311316



Photo 5. Looking north across the location. Disassembled pumpjack remains on location.



Photo 6. Photo taken on the east side of the location. Unused electrical meter.