

# Final Reclamation and Stormwater Inspection

October 31, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC -  
10261

Location ID: 433247

Well Name: Swan #21-44

Inspection Document #: 718601127

Washington County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Swan #21-44  
Location ID: 433247



**Photo 1.** Picture taken at the entrance to the access road. A patch of undesirable weed kochia is present near the entrance. Desirable vegetation is present on most portions of the access road.



**Photo 2.** Picture taken at midpoint of access road. looking southwest towards the location. A 30 ft patch of undesirable weed kochia with less desirable vegetation establishment than the surrounding reference area is present.



Inspection Photos  
Location Name: Swan #21-44  
Location ID: 433247



**Photo 3.** Looking north along the east edge of the location. The location is fenced. The fence is loose and down in places. Vegetation on the location is not reflective of the surrounding reference area (reference area right side of picture).



**Photo 4.** Looking west across the location. Perennial vegetation is present on location. The vegetation does not appear to have reached 80% coverage of the reference area.



Inspection Photos  
Location Name: Swan #21-44  
Location ID: 433247



**Photo 5.** Looking north from the wellbore. Desirable vegetation is present on location but does not appear to have reached 80% coverage of the reference area. Vegetation on the location is not reflective of the surrounding reference area. Vegetation on location appears to be predominantly russian wildrye, crested wheatgrass and smooth brome which were not observed in significant amounts in the reference area.



**Photo 6.** Looking west from wellbore. See photo 5 comments.



Inspection Photos  
Location Name: Swan #21-44  
Location ID: 433247



**Photo 7.** Looking south from wellbore. See photo 5 comments.



**Photo 8.** Looking east from wellbore. See photo 5 comments.



Inspection Photos  
Location Name: Swan #21-44  
Location ID: 433247



**Photo 9.** Picture taken on the west side of the location looking east. Portions of the location have lower vegetative coverage.



**Photo 10.** Reference vegetation to the west of the well location. Vegetation is primarily buffalograss, blue gramma and other native perennial species. Cheatgrass is also present in the reference area.