

Inspection Photos  
HSR-HOBE STATE-63N62W  
Location ID 330074



Photo 1 – Location sign

Photo 2 - Repairs to bird netting have torn on western produced water tank

Inspection Photos  
HSR-HOBE STATE-63N62W  
Location ID 330074



**Photo 3 – Repairs to bird netting have torn on western produced water tank (hand for scale).**

**Photo 4 - Western produced water tank**

Inspection Photos  
HSR-HOBE STATE-63N62W  
Location ID 330074



**Photo 5 – Oil noted on water in bottom of western produced water tank.**



**Photo 6 - Repairs on eastern produced water tank remain intact.**