

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404356403

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers
Address: <u>1099 18TH STREET SUITE 1500</u>		Phone: <u>(970) 304-5000</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>()</u>
Contact Person: <u>Dan Peterson</u>	Email: <u>RBUEUF27@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 22758 Initial Form 27 Document #: 403005992

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-24108</u>	County Name: <u>WELD</u>
Facility Name: <u>WEBSTER B 6-17</u>	Latitude: <u>40.428847</u>	Longitude: <u>-104.587487</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SENE</u>	Sec: <u>6</u>	Twp: <u>5N</u>	Range: <u>64W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>
Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-24107</u>	County Name: <u>WELD</u>
Facility Name: <u>WEBSTER B 6-7</u>	Latitude: <u>40.428791</u>	Longitude: <u>-104.587504</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SENE</u>	Sec: <u>6</u>	Twp: <u>5N</u>	Range: <u>64W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: LOCATION	Facility ID: 332980	API #:	County Name: WELD
Facility Name: WEBSTER B-65N64W 6SENE	Latitude: 40.428847	Longitude: -104.587487	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: SENE	Sec: 6	Twp: 5N	Range: 64W Meridian: 6 Sensitive Area? Yes

Facility Type: SPILL OR RELEASE	Facility ID: 491663	API #:	County Name: WELD
Facility Name: WEBSTER B 6-17	Latitude: 40.428856	Longitude: -104.587502	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: SENE	Sec: 6	Twp: 5N	Range: 64W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Industrial Land

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

High Priority Habitat - Aquatic Native Species Conservation Waters
 Freshwater Emergent Wetlands 0.01mi W, 0.14mi SW, 0.18mi NE
 Riverine 0.02mi W, 0.13mi SW, 0.04/0.23mi NW, 0.09mi N, 0.05mi NE, 0.06mi E, 0.17mi SE
 Freshwater Pond 0.07/0.13mi E, 0.07mi NW, 0.18mi W
 Riparian Forested Shrub 0.04mi W, 0.07mi N, 0.15mi SW
 Farm Structures 0.07/0.09/0.1mi W, 0.11/0.12/0.14/0.23mi SW, 0.2/0.23mi E
 Residential 0.09mi SW, 0.18mi E

SITE INVESTIGATION PLAN

TYPE OF WASTE:

<input checked="" type="checkbox"/> E&P Waste	<input type="checkbox"/> Other E&P Waste	<input type="checkbox"/> Non-E&P Waste
<input checked="" type="checkbox"/> Produced Water	<input type="checkbox"/> Workover Fluids	
<input checked="" type="checkbox"/> Oil	<input type="checkbox"/> Tank Bottoms	
<input checked="" type="checkbox"/> Condensate	<input type="checkbox"/> Pigging Waste	
<input type="checkbox"/> Drilling Fluids	<input type="checkbox"/> Rig Wash	
<input type="checkbox"/> Drill Cuttings	<input type="checkbox"/> Spent Filters	
	<input type="checkbox"/> Pit Bottoms	
	<input type="checkbox"/> Other (as described by EPA)	

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab Analysis or Field Screening, if encountered.
Yes	SOILS	Refer to Tables and Figures	Lab Analysis and Field Screening

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to WEBSTER B 6-7 wellhead cut and cap and flowline removal. Approximately 167' of flowline was abandoned in place (ECMC doc#403540450) on 5/1/2023. The wellhead was cut and capped per ECMC rules on 2/17/2023. Additionally, soil samples were collected at any points of material change and/or hammer unions, as well as at the bell holes on either side of a waterway.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the WEBSTER B 6-17 wellhead cut and cap and flowline removal. Approximately 145' of flowline will be removed. The ECMC will be updated in a supplemental Form 27 if a portion of the flowline is abandoned in place due to field constraints. The wellhead was cut and capped per ECMC rules on 8/21/2025. Additionally, soil samples will be collected at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of the waterway, as applicable to abandonment type.

A site investigation was conducted pursuant to ECMC Rule 911 at the WEBSTER B-65N64W Tank Battery location on 8/20/2025. Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), and at the separator(s).

The Field Qualitative Criteria Checklist was utilized during WEBSTER B 6-17 wellhead and tank battery decommissioning activities and no visual and olfactory impacts were observed. Based on laboratory analytical data, historical releases were discovered on September 16, and September 23, 2025, under F19 Document Numbers 404357143 and 404392154, for elevated Table 915-1 organics at sample locations FL01-R@4.5' and 22758-WV-01-SO-4-20250820, respectively.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Five grab soil samples were collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavations and at the flowline terminus. Soil samples were field screened at the N-E-S-W sides of the wellheads. Soil samples will be taken along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. Ten grab confirmation soil samples were collected from the produced water vessel excavation, beneath the ground oil tanks, and at the risers for the flowlines and dumplines of the separators. Samples were and will be analyzed by a certified laboratory for organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were and will be analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation a grab groundwater sample will be collected and analyzed for all organic compounds and inorganic parameters per ECMC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the wellhead and flowline areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Flowline Closure and Wellhead Closure Checklists were utilized and filled out during the abandonment process. Detailed summaries of wellhead and tank battery decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, are attached to this Form 27.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 13

Number of soil samples exceeding 915-1 7

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 700

NA / ND

-- Highest concentration of TPH (mg/kg) 16.8

-- Highest concentration of SAR 0.723

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 6

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

[Empty text box]

Were background samples collected as part of this site investigation?

Seven background soil samples were collected from six locations near the wellhead and tank battery on 8/20 and 8/21/2025 and analyzed for Table 915-1 metals in soil and Soil Suitability for Reclamation parameters per ECMC Table 915-1. The background soil samples were collected from a depth of 3, 5, and 6 feet below ground surface (ft bgs). The lithology between the site and background locations was observed to be well graded sands. Additional background samples will be collected to determine site specific background concentrations of pH, arsenic, barium, cadmium, lead, and selenium.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

Concurrently with the remedial excavation that is proposed in the Remedial Action Plan section of this Form 27, background soil samples will be collected to determine if elevated levels of pH, arsenic, barium, cadmium, lead, and selenium are attributed to native soil conditions at the site. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. Proposed background soil sample locations are shown on the attached proposed excavation map.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The naphthalene, benzo(a)anthracene, benzo(a)pyrene, 1-methylnaphthalene, and 2-methylnaphthalene exceedances observed at sample locations (22758-PV-02-SO-4-20250820, 22758-WV-01-SO-4-20250820, and FL01-R@4.5') on 8/20 and 8/21/2025 will be removed through a remedial excavation in accordance with the proposed excavation map attached to this Form 27. Soil samples will be collected from the base and sidewalls of the respective final excavation extents and will be submitted for analysis of the full ECMC Table 915-1 suite.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Concurrently with the remedial excavation that is proposed in the Remedial Action Plan section of this Form 27, background soil samples will be collected to determine if elevated levels of pH, arsenic, barium, cadmium, lead, and selenium are attributed to native soil conditions at the site. Background soil samples will be analyzed by a certified laboratory for analysis of metals per ECMC Table 915-1 and soil suitability parameters including pH, EC, SAR, and boron. Proposed background soil sample locations are shown on the attached proposed excavation map.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during site investigation activities.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other _____

Request Alternative Reporting Schedule:

Semi-Annually Annually Other _____

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Decommissioning Sample Summary, Supplemental Source Mass Removal and Site Investigation Proposals

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 02/17/2023

Proposed date of completion of Reclamation. 10/31/2027

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 02/03/2022

Actual Spill or Release date, or date of discovery. 09/16/2025

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/17/2023

Proposed site investigation commencement. 01/13/2026

Proposed completion of site investigation. 05/13/2026

REMEDIAL ACTION DATES

Proposed start date of Remediation. 05/13/2026

Proposed date of completion of Remediation. 11/06/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the decommissioning of the WEBSTER B 6-17 wellhead and the WEBSTER B-65N64W tank battery and necessity for remedial excavation activities adjacent to the wellhead and tank battery.

OPERATOR COMMENT

This Form 27 is being submitted to include a 4Q 2025 update for the WEBSTER B 6-17 wellhead and WEBSTER B-65N64W tank battery (REM #22758) and decommissioning results and historic reportable releases discovered at the former wellhead and tank battery location. A proposal to excavate the naphthalene, benzo(a)anthracene, benzo(a)pyrene, 1-methylnaphthalene, and 2-methylnaphthalene exceedances identified during decommissioning (soil samples 22758-PV-02-SO-4-20250820, 22758-WV-01-SO-4-20250820, and FL01-R@4.5') is presented in the Remedial Action Plan section of this Form 27. Based on laboratory analytical data received on 9/16 and 9/23/2025 historic releases were reported for sample locations FL01-R@4.5' and 22758-WV-01-SO-4-20250820 under Form 19 Document Numbers 404357143 and 404392154, respectively. The Form 19 Document Number 404392154 remains "In Process" at the time of this F27 submittal and the spill ID will be included on a subsequent Form 27.

Seven background soil samples were collected from six locations near the wellhead and tank battery on 8/20 and 8/21/2025 and analyzed for Table 915-1 metals in soil and Soil Suitability for Reclamation parameters per ECMC Table 915-1. The background soil samples were collected from a depth of 3, 5, and 6 feet below ground surface (ft bgs). The lithology between the site and background locations was observed to be well graded sands. Additional background samples will be collected to determine site specific background concentrations of pH, arsenic, barium, cadmium, lead, and selenium.

The WEBSTER B 6-17 flowline is currently planned for future removal, at which time soil sampling and screening samples will be taken along the flowline at any points of material change and/or hammer unions, and directional changes. Pursuant to the flowline removal, all laboratory analytical samples will be analyzed for full ECMC Table 915-1 contaminants of concern. Additional SSI activities will be proposed (as applicable) on a future Form 27 if further investigation is required.

Pursuant to Rule 913.e, quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Kayla White, P.E.

Title: Environmental Consultant

Submit Date: _____

Email: cvx-pm@cdhconsult.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 22758

COA Type

Description

0 COA	
-------	--

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404416184	SITE INVESTIGATION REPORT
404416185	LABORATORY ANALYTICAL REPORT
404416186	LABORATORY ANALYTICAL REPORT
404416187	LABORATORY ANALYTICAL REPORT
404416192	LABORATORY ANALYTICAL REPORT
404416195	LABORATORY ANALYTICAL REPORT
404416205	LABORATORY ANALYTICAL REPORT
404435765	SITE INVESTIGATION REPORT

Total Attach: 8 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)