

Inspection Photos
Location Name: State 16-33
API Number: 125-07729



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: State 16-33
API Number: 125-07729



3. Belt guard inside fencing at well location.



4. Removed prime mover motor inside fencing at well location.

Inspection Photos
Location Name: State 16-33
API Number: 125-07729



5. Well location overview.



6. View of Gas Meter Run Shed.

Inspection Photos
Location Name: State 16-33
API Number: 125-07729




7. Roof damage on Gas Meter Shed.



8. Gas meter inside meter shed.

Inspection Photos
Location Name: State 16-33
API Number: 125-07729



9. Calibration/Test Log inside Meter Shed.

10. Gathering location overview.