

Inspection/Audit Photos

Location: UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 11/11/2025



Photo # 4035 Entrance to location



Photo # 4036 Location

Inspection/Audit Photos

Location: UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 11/11/2025




Photo # 4037 Location



Photo # 4040 Location

Inspection/Audit Photos

Location: UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 11/11/2025



Photo # 4044 SE corner of location



Photo # 4045 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 11/11/2025



Photo # 4046 NW corner of location



Photo # 4047 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 11/11/2025



Photo # 4050 Insufficient erosion control on lease road; rill erosion cutting down lease road

Photo # 4051 Insufficient erosion control on lease road; rill erosion cutting down lease road