

Inspection Photos

November 12th, 2025

Operator: Logos Operating LLC

Location ID: 325365

Inspection Document #: 714002786

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Docar GU 2A
Location ID: 325365

November 12, 2025
101° E



Photo 1. View of the well pad taken from the access point facing center.

November 12, 2025
64° NE



Photo 2. Unused shed on the location has been removed .



November 12, 2025
50° NE



Photo 3. View of eastern interim reclamation area.



November 12, 2025
310° NW



Photo 4. View of location northern cut slope which remains with bare loose soils and no vegetation establishment.

November 12, 2025
332° NW



Photo 5. View of gully erosion forming on the location cut slope.

