

**Inspection Photos**  
**Location Name: Castor 7-59-11-2 PAD**  
**Location ID: 468847**



**Photo 1 – 7-59-11-2-1 Wellhead**

**Photo 2 – Wellhead Sign**

Inspection Photos  
Location Name: Castor 7-59-11-2 PAD  
Location ID: 468847



Photo 3 – Unused Gas Meter and Automated Equipment

Photo 4 – Unmarked Riser

Inspection Photos  
Location Name: Castor 7-59-11-2 PAD  
Location ID: 468847



Photo 5 – Unmarked Riser



Photo 6 – Unmarked Riser

**Inspection Photos**  
**Location Name: Castor 7-59-11-2 PAD**  
**Location ID: 468847**



**Photo 7 – Separators**

**Photo 8 – Separators**

**Inspection Photos**  
**Location Name: Castor 7-59-11-2 PAD**  
**Location ID: 468847**



**Photo 9 – ECD**



**Photo 10 – Tank Battery**

**Inspection Photos**  
**Location Name: Castor 7-59-11-2 PAD**  
**Location ID: 468847**



**Photo 11 – Tank Battery Signs**

**Photo 12 – Tank Battery**

**Inspection Photos**  
**Location Name: Castor 7-59-11-2 PAD**  
**Location ID: 468847**



**Photo 13 – Gas Meter**

**Photo 14 – Compressor**

**Inspection Photos**  
**Location Name: Castor 7-59-11-2 PAD**  
**Location ID: 468847**



**Photo 15 – Separators**