

Inspection Photos  
Location Name: R M R Ranch 2  
API Number: 125-07290



1. Lease sign at gathering location.

2. Content/Quantity/Hazard sign at produced water tank.

Inspection Photos  
Location Name: R M R Ranch 2  
API Number: 125-07290



3. View of Production tank at remote gathering location. Note dried vegetation.



4. Gathering location overview.