

Audit Photos


Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/28SESW

Location ID: 312392

Date: 11/6/2025



Location Overview – Photo #01461



Location/Weeds – Photo #01464

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/28SESW

Location ID: 312392

Date: 11/6/2025



Location/Weeds – Photo #01462



Location/Weeds – Photo #01470

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/28SESW

Location ID: 312392

Date: 11/6/2025



Location/Weeds – Photo #01466



Location/Weeds – Photo #01467

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/28SESW

Location ID: 312392

Date: 11/6/2025



Location/Weeds – Photo #01469



Wildlife Entry Hazard – Photo #01463

Audit Photos

Location Name: FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/28SESW

Location ID: 312392

Date: 11/6/2025



Stored/Unused Equipment/Weeds – Photo #01468