

Final Reclamation Inspection

October 20, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 466414

Inspection Document #: 718800977

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: MCINTOSH-66N64W/23SESE

Location ID: 466414



Photo 1. Photo taken of the access road to the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the tank battery location, facing east. Photo illustrates that vegetation establishment does not meet Rule 1004 standards.



Inspection Photos

Location Name: MCINTOSH-66N64W/23SESE

Location ID: 466414



Photo 3. Photo taken of the tank battery location, facing northeast. See comments under Photo 2.



Photo 4. Photo taken of the tank battery location, facing south. See comments under Photo 2.



Inspection Photos
Location Name: MCINTOSH-66N64W/23SESE
Location ID: 466414



Photo 5. Photo taken of the tank battery location, facing west. See comments under Photo 2.



Photo 6. Photo taken of the reference area to the tank battery location, east of the location, facing north. Photo illustrates alfalfa cropland.

