

Final Reclamation Inspection

October 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 331976

Inspection Document #: 718800967

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COOPER #23-12
Location ID: 331976



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place. However, vegetation has not established to Rule 1004 standards at the location as weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: COOPER #23-12
Location ID: 331976



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: COOPER #23-12
Location ID: 331976



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing northeast. Photo illustrates that the access road does not meet Rule 1004 standards as weedy annual vegetation was observed.

Inspection Photos
Location Name: COOPER #23-12
Location ID: 331976



Photo 7. Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass vegetation that has been grazed.