

Final Reclamation Inspection

October 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 332985

Inspection Document #: 718800973

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FOSS-66N64W/23SENE
Location ID: 332985



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation has taken place and the multi-well location is in a land use change.



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: FOSS-66N64W/23SENE
Location ID: 332985



Photo 3. Photo taken of the multi-well location, facing south.
See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west.
See comments under Photo 1.

Inspection Photos
Location Name: FOSS-66N64W/23SENE
Location ID: 332985



Photo 5. Photo taken of the tank battery location, facing southwest. Photo illustrates that the tank battery does not meet Rule 1004 standards as weedy annual vegetation was observed across the location.



Photo 6. Photo taken of the tank battery location, facing north. See comments under Photo 5.

Inspection Photos
Location Name: FOSS-66N64W/23SENE
Location ID: 332985



Photo 7. Photo taken of the reference area to the location, west of the location, facing northwest. Photo illustrates perennial grass and weedy annual vegetation.