

# Final Reclamation Inspection

October 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329778

Inspection Document #: 718800979

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SIDWELL #26-1G4  
Location ID: 329778



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that the location meets Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: SIDWELL #26-1G4  
Location ID: 329778



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: SIDWELL #26-1G4  
Location ID: 329778



**Photo 5.** Photo taken of the reference area to the location, north of the location, facing west. Photo illustrates perennial grass cropland.