

# Final Reclamation Inspection

October 20, 2025

Operator: NOBLE ENERGY INC – 100322

Location ID: 447349

Inspection Document #: 718800985

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DCD FARMS 1-26,A  
26-2,7,SIDWELL 26-/1G4,8  
Location ID: 447349



**Photo 1.** Photo taken of the tank battery location, facing north. Photo illustrates that location does not meet Rule 1004 standards as gravel, bare ground, and weedy annual vegetation were observed across the location.



**Photo 2.** Photo taken of the tank battery location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: DCD FARMS 1-26,A  
26-2,7,SIDWELL 26-/1G4,8  
Location ID: 447349



**Photo 3.** Photo taken of the tank battery location, facing west. See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing southwest. See comments under Photo 1.

Inspection Photos  
Location Name: DCD FARMS 1-26,A  
26-2,7,SIDWELL 26-/1G4,8  
Location ID: 447349



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates gravel remains on the location.



**Photo 6.** Photo taken of the reference area to the tank battery location, east of the location, facing north. Photo illustrates perennial grass vegetation.

