

# Inspection Photos

11/14/2025

Operator: Chevron USA Inc #16700

Location ID: 398400

Inspection Doc: 719200457

Rio Blanco County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 398400



**Photo 1:** Photos showing a general overview of the location south of the access road looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 398400



**Photo 2:** Photos showing a general overview of the location south of the access road looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 398400



**Photo 3:** Photos showing examples of degraded straw wattles and wooden stakes that are scattered throughout the location. Comply with Rule 606.d. and remove debris.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 398400



**Photo 4:** Photos showing the access road leading to the electrical tower.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources