

Audit Photos

Location Name: UTAH GAS CORP, SOUTH CANYON-FEDERAL-67S103W/8NWNW

Location ID: 322295

Date: 11/11/2025



Nov 11, 2025 at 12:05:16
+39.472442,-108.909534
De Beque CO 81630
United States



Nov 11, 2025 at 12:05:34
+39.472309,-108.909504
De Beque CO 81630
United States

Location Overview – Photo #01525

Location – Photo #01526

Audit Photos

Location Name: UTAH GAS CORP, SOUTH CANYON-FEDERAL-67S103W/8NWNW

Location ID: 322295

Date: 11/11/2025



Location – Photo #01529



Location – Photo #01528

Audit Photos

Location Name: UTAH GAS CORP, SOUTH CANYON-FEDERAL-67S103W/8NWNW

Location ID: 322295

Date: 11/11/2025



Nov 11, 2025 at 12:07:03
+39.472050,-108.909458
De Beque CO 81630
United States



Nov 11, 2025 at 12:18:06
+39.468826,-108.911757
De Beque CO 81630
United States

Wildlife Entry Hazard – Photo #01530

Lease Road Erosion – Photo #01532

Audit Photos

Location Name: UTAH GAS CORP, SOUTH CANYON-FEDERAL-67S103W/8NWNW

Location ID: 322295

Date: 11/11/2025



Lease Road Erosion – Photo #01534



Lease Road Erosion – Photo #01535